

**CAREFULLY CHECK YOUR MOORING LINES
- WEAKNESSES MAY NOT BE OBVIOUS**

This illustrates how hidden a defective line can be. Thimble was rusted and worn through to the point where chafing resistance to the shackle was about gone. Only a matter of time until the nylon line wears through.

